

Oil Field Environmental Incident Summary

Incident: 20140114112920 **Date/Time of Notice:** 01/14/2014 11:18

Responsible Party: Denbury Onshore LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CHSU 44C-29SH 26

Field Name: CEDAR HILLS

Well File #: 16150

Date Incident: 1/13/2014 **Time Incident:** 10:00

Facility ID Number:

County: BOWMAN

Twp: 132

Rng: 106

Sec: 29

Qtr: SE SE

Location Description: Leak surfaced approximately 0.25 miles east of 44C-29NH16 location. In SWSW 28-132-106.

Submitted By: Josh Cuppy

Received By:

Contact Person: Josh Cuppy
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Miles

Distance Nearest Water Well: 2 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	barrels	0.5	barrels	0.5	barrels
Brine	0.5	barrels	0.5	barrels	0.5	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/17/2016

Clean Up Concluded: 5/4/2015

Risk Evaluation:

None

Areal Extent:

Leak impacted an approximate 20 ft area on surface

Potential Environmental Impacts:

None

Action Taken or Planned:

Impacted soil will be removed and disposed of during excavation of area for repair.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/15/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from pipeline leak, off location. Followup is necessary.

Date: 1/23/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/23/14 - 12:15 on location. Leak site is at location listed. Contact with company rep revealed that leak was caused by a cross-threaded joint in the buried line. Roberts requested line history and photos/description of the joint. Leak has been repaired, backfilled and surface restored. Location is on edge of a sculpted terrain pasture. Will need to follow up in spring '14 to determine whether vegetation in area is re-established, or leak has affected a larger area than currently remediated.

Date: 6/9/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/9/2015 at 19:23, on location. Area vegetation regrowing, disturbed soil on northside of wellpad lease road has been tilled and replanted.